

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

UNIT '	TYPE:						
Lined MSWLF	LCID	X	YW	Transfer	Compost	SLAS	COUNTY: Moore
Closed MSWLF	HHW		White goods	Incin	T&P	FIRM	LCID NOTIFICATION I.D. NO.: N0659
CDLF	Tire T&P / Collection		Tire Monofill	Industrial Landfill	DEMO	SDTF	FILE TYPE: Compliance

Date of Audit: May 9, 2011

Date of Last Audit: March 24, 2010

FACILITY NAME AND ADDRESS:

Eddie Cagle LCID Landfill 256 Omni Drive West End, North Carolina 27376

GPS COORDINATES: N: 35.2186 W: -79.5806

FACILITY CONTACT NAME AND PHONE NUMBER:

Eddie Cagle, Owner & Operator, EdScape, Inc. (910) 673- 0301

FACILITY CONTACT ADDRESS:

P.O. Box 183 West End, North Carolina 27376

AUDIT PARTICIPANTS:

Joseph Cagle, Site attendant Robert Hearn, Solid Waste Section

STATUS OF PERMIT:

LCID Landfill Notification Form filed for recordation at Moore County Register of Deeds' office: June 20, 2005

LCID Landfill Notification letter issued to Eddie Cagle: July 8, 2005

PURPOSE OF AUDIT:

Comprehensive audit

NOTICE OF VIOLATION:

(none)

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$5,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. If the violation(s) noted here continue, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

STATUS OF PAST NOTED VIOLATIONS:

(none)

AREAS OF CONCERN AND COMMENTS:

- 1. This facility is owned by Eddie and Jayne Cagle and operated by EdScape, Inc. The facility is not open to the public, and does not keep regular operating hours. Inspected facility accompanied by Mr. Joseph Cagle.
- 2. Observed appropriate waste types in the landfill disposal area; no unpermitted waste was observed during the inspection.
- 3. Observed that the limits of the two-acre disposal area are marked with flagged stakes. The landfill is located on a former soil borrow area.
- 4. Observed that the current landfill 'working-face' area had too much exposed waste. Take actions to apply soil to cover the inactive working face area.
- 5. Observed that the top surface of the landfill appeared to have adequate soil cover and was graded to allow proper drainage of stormwater runoff.
- 6. Observed that the facility access road was in good shape.
- 7. Observed no leachate or severe erosion problems at the site during the inspection.
- 8. Rule 15A N.C. Admin. Code 13B .0566(16) requires that a sign be posted at the facility entrance showing the contact name and phone number in case of an emergency. Observed that no such sign was in place at the facility entrance. Please take actions to post a sign at the entrance with the required information.

Phone: (919) 508-8525

Please contact me at the number below if you have any questions about this audit report.

Robert Hearn

Environmental Senior Specialist

Regional Representative

cc:

Jason Watkins, Central District Supervisor

Shawn McKee, Compliance Officer

processor and the second secon			
Delivered on: 5/27/11 by	Hand delivery	x US Mail	Certified Mail